

Soundtracs - Digico(UK) Ltd. unit 10 Silverglade Business Park Chessington Surrey KT9 2QL England  
Tel: +44 1372 845600 Fax: +44 1372 845656 email: [support@digiconsoles.com](mailto:support@digiconsoles.com)

---

## **S21 Console Upgrade from V1.2 or V1.3 to 1.3.3**

Please see below for links and details of the latest S21 software upgrade.

**There is a now a Version 1.3.3 software upgrade available for the S21 – this replaces V1.3**


Please read and follow the upgrade instructions below carefully.  
This version includes a number of bug fixes – please refer to the Release Notes for details  
This version is compatible with sessions from V1.2 and V1.3

**The following instructions assume that you are upgrading a console that is running S21 software version 1.2**

**NOTE: If you are upgrading from V1.3 there is no requirement to upgrade worksurface or DMI card code**

### **Software upgrade**

1. Download the ZIP file (see link below) and extract/unzip the file named update.dcu on your computer
2. Copy the unzipped file to the root folder of a USB key (please ensure that the file is in the ROOT folder and not in a sub folder – also ensure that it is called update.dcu)
3. Switch the console off
4. Insert the USB key in the console USB port
5. Hold down the “Overview” button on the console worksurface (see image below)



6. Switch the console on and keep the overview button held for about 5 seconds and then release it
7. You should then see a series of icons on the screen starting with a clock icon
8. Wait for the console application to boot
9. Open the main menu and check the version number at the bottom of the screen – it should be V1.3.3
10. Power cycle the console
11. Upgrade complete
12. Now proceed to the Worksurface and DMI Card Firmware Upgrade procedure below

### **Worksurface Firmware upgrade**

There is **new worksurface code (V53)** in the package that will need to be applied to both surfaces.  
The procedure is as follows:


For one section at a time:

1. Power off
2. Power on while holding down both the 1<sup>st</sup> and 10<sup>th</sup> channel mute buttons down until you see the engine icon appear on screen and then release the buttons.
3. Wait until the App starts and you should then see a progress display indicating that the upgrade has started – wait for this to finish
4. Power off again and repeat the above procedure for the second section holding the 1<sup>st</sup> and 10<sup>th</sup> channel mutes in that section (Mutes 11 and 20)
5. Wait for the update to finish and power cycle the console again
6. Open the Main Menu > Diagnostics view and check that both surfaces report code Version 53

## DMI Card - Firmware upgrade

There is new DMI card code (V82 for ADC, DAC, AES, DANTE, AVIOM and V125 for MADI DMI plus FPGA codes relevant to the DMI cards present in the console) embedded in this version of software so when the software application upgrade is complete, please go to the Main Menu>System>DMI cards and upgrade any installed DMI cards using the upgrade buttons on that page

1. If an installed DMI card requires an upgrade, the button below the card display will say "Update DMI Card".
2. Press this button to upgrade the card and wait until the process is completed.
3. When the card has been successfully updated, check that the "Current" and "Available" code versions match.
4. Now power cycle the console to complete the procedure.



The S21 V1.3.3 Console software package (including this Technical Note) is available for download at:  
[www.digico.org/S21\\_Downloads/S21\\_V1\\_3\\_3\\_Web\\_Updater.zip](http://www.digico.org/S21_Downloads/S21_V1_3_3_Web_Updater.zip)

If you have any questions please call us - UK Office hours are 8.30AM to 5.30PM (GMT) Monday to Friday. Whilst we do offer an "Out Of Hours" Support service during evenings and weekends, there may be a longer delay in response during those times so please bear this in mind.