



SD Series Software V760 Download Information

V760 Installers are not available for download directly from the DiGiCo Website. Please contact your local distributor.

To find your local distributor, please click on the link below.

http://www.digico.biz/docs/distributors_clients/index.php?group=Distributor

Release Notes

These release notes cover new features and fixes from V726-760
V760 replaces V726 as the production release.

IMPORTANT NOTE:

When using multiple consoles on an Optocore loop, please ensure that all consoles are running the same version of software and same Optocore Firmware.

V760 Will only load sessions last saved in V300 or later.

New Features

Support for Orange box and DMI Cards

Support added for Clearcom Progrid Devices.

Dynamic EQ panels will remain open when scrolling across channels.

Fixes

The Macro system was ignoring incoming GPI Open messages.

Using a macro to solo a stereo or bigger buss would leave the left leg of the buss unsoloed.

Recalling mix presets after a restructure where the channel count had been adjusted could cause an Access Violation.

All three gain reduction bands on the Multiband compressor bridge or floating meters were showing the mid band gain reduction.

Trim offset levels were being reset to 0dB if gain tracking was enabled on session load.

Any digital trim values lower than -20dB were being set to -20dB on session load.

The Optocore system was reporting unnecessary remaps when not loading startup sessions.

In Theatre, the auto update of channel direct outs was incorrectly affected by Output device scope settings.

If snapshots were being recalled by timecode, any MIDI messages that were being triggered by snapshot recall would be duplicated.

Using Touch turn, values greater than 23 frames could not be entered in transport control.

